

Date and Time of inspection 11.03.24 1200 hrs.			Inspected by Ann Stafford					
Coleorton Parish Council								
Routine Play Area Inspection Report - Weekly								
Play Area	Play area sign	Dog bin Litter bin	Fence/gate boundary inc play area fence	Seating	Swings	Climbing Frame	Rope Climb	Spring Seat
Zion Hill, Peggs Green	OK	OK	OK*	OK	OK	OK	OK	OK
Forrester Close (NWLDC)								
<p>This is a weekly visual check of the named area. The equipment will be in line with current ROSPA recommendations for visual evidence of damage. If anything is noticed, then further investigation in terms of checking of the equipment, repairs instructed, area closed etc will be put in place. Depending of the severity of any issue, will depend whether there is a need to close the area. All issues will be recorded, and reported direct to the Clerk and necessary action agreed.</p>								
Clerks' comments								

Climbing Frame
Swings
Rope Climb
Seat on spring
Fence

*Boundary

Establish ownership of fence.
Also need to decide how to deal with possible trip hazard at entry to field (metal kissing gate). This is a public footpath so will get a great deal of traffic not intended for the play area
Both goal posts loose in ground.
Visual boundary inspection