

<b>Date and Time of inspection 28.03.24 1330 hrs.</b>			<b>Inspected by</b> Ann Stafford					
<b>Coleorton Parish Council</b>								
<b>Routine Play Area Inspection Report - Weekly</b>								
<b>Play Area</b>	<b>Play area sign</b>	<b>Dog bin Litter bin</b>	<b>Fence/gate boundary inc play area fence</b>	<b>Seating</b>	<b>Swings</b>	<b>Climbing Frame</b>	<b>Rope Climb</b>	<b>Spring Seat</b>
Zion Hill, Peggs Green	OK	OK	OK*	OK	OK	OK	OK	OK
Forrester Close (NWLDC)								
<p><b>This is a weekly visual check of the named area. The equipment will be in line with current ROSPA recommendations for visual evidence of damage. If anything is noticed, then further investigation in terms of checking of the equipment, repairs instructed, area closed etc will be put in place. Depending of the severity of any issue, will depend whether there is a need to close the area. All issues will be recorded, and reported direct to the Clerk and necessary action agreed.</b></p>								
Clerks' comments								

Climbing Frame  
Swings  
Rope Climb  
Seat on spring  
Fence

\*Boundary

Establish ownership of fence.

Also need to decide how to deal with possible trip hazard at entry to field (metal kissing gate). This is a public footpath so will get a great deal of traffic not intended for the play area

Both goal posts loose in ground.

Boundary inspection